








INNER WIRES OF RESISTANCE THERMOMETERS

number of precision winding	circuit of inner wires			
	2-wire	3-wire	4-wire	2-wire with loop
Pt 100				
2 x Pt 100				
3 x Pt 100	